

## SPEC SHEET + MEASUREMENTS



### CornerStone® ANSI 107 Class 3 Long Sleeve Snag-Resistant Reflective T-Shirt. CS409

#### Product photo



Stay safer on the jobsite in this high-visibility t-shirt that works as hard as you do.

- ANSI/ISEA 107 Class 3 certified
- 3.7-ounce, 100% polyester
- Wicks moisture
- UPF rating of 30+
- Resists snags
- Rib knit crewneck and cuffs
- 2-in. wide reflective taping on front, back and sleeves
- Left chest pocket for pen and notes

#### CARE INSTRUCTIONS

Do not bleach, iron or dry clean. Tumble dry low. Permanent press.

#### Sketches



front



back

# SPEC SHEET + MEASUREMENTS



CornerStone® ANSI 107 Class 3 Long Sleeve Snag-Resistant Reflective T-Shirt. CS409

## PRODUCT MEASUREMENTS

|                                | XS     | S      | M      | L      | XL     | 2XL    | 3XL    | 4XL    |
|--------------------------------|--------|--------|--------|--------|--------|--------|--------|--------|
| Body Length at Back            | 29 1/2 | 30     | 30 1/2 | 31     | 32     | 33     | 33 1/2 | 34     |
| Chest                          | 20     | 21 1/2 | 23     | 24 1/2 | 26     | 27 1/2 | 29 1/2 | 31 1/2 |
| Sleeve Length from Center Back | 33 3/4 | 34 1/2 | 35 1/4 | 36     | 36 3/4 | 37 1/2 | 38 1/4 | 39     |

- Body Length at Back:** Measured from high point shoulder to finished hem at back.
- Chest:** Measured across the chest one inch below armhole when laid flat.
- Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

## SIZE CHARTS

|       | XS    | S     | M     | L     | XL    | 2XL   | 3XL   | 4XL   | 5XL   | 6XL   | 7XL   | 8XL   | 9XL   | 10XL  |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Chest | 32-34 | 35-37 | 38-40 | 41-43 | 44-46 | 47-49 | 50-53 | 54-57 | 58-60 | 61-63 | 64-66 | 67-69 | 70-72 | 73-75 |

# SPEC SHEET + MEASUREMENTS



CornerStone<sup>®</sup> ANSI 107 Class 3 Long Sleeve Snag-Resistant Reflective T-Shirt. CS409

## HOW TO MEASURE

---



### CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## COLORS

---



Safety Orange Safety Yellow